

FOREVER SOLVENT TRANSPARENT 161 (CUTTABLE)

Solvent transfer media for cotton, polyester and polycotton blends.

Weeding Tool ? See - www.forevertransferpaper.com/weeding-tool

APPLICATION

1. Print and cut your design.
2. Use your weeding tool to remove any excess transfer.
3. Position your textile onto your heat press.
4. Position FOREVER Solvent Transparent 161 onto your textile with the printed side facing down.
5. Press for 20 seconds.
6. Peel off the transfer paper.

PRESS SETTINGS

Pressure · High - 5bar (70 PSI)

Temperature · 200°C (390°F)

Time · 20 seconds

PRINT SETTINGS

Image Mode · Mirror/Reverse

WASH & CARE

- ♦ Warm wash up to 40·C

These instructions are based on using a professional Adkins swing-around press, adjustments may be required depending on the press you are using.

This transfer paper is not suitable for application using a household iron.

This transfer paper is suitable only for Solvent Printers.

Are you experiencing problems with this transfer media?

Don't panic, it does work.

Call us on 01244 541 647 or E-Mail info@forevertransferpaper.com